


- Q101: MPS 94 (MC 25C192310)
 Q102, Q103: 3SK 45 - L3SK73 35K59
 Q104: 2SK 19, JF10335
 Q105: MF5 9623 (I) 25C 373
 Q106: MPS 9623 (H) 25C 372(Y)
 Q201, Q202, Q203: MPS 9634 (C,D) 25C 733
 Q206: MPS 9418 (T) 25C 509
 Q207: MPS 9681 (T) 25A 495
 Q301: MPS 9426 (BC) 25C 388 A
 Q302: 25C1957, 25C2314, 25C1678
 Q303: 25C1306, 25C2078, 25C 495(T)

- 1S 953, MA150, KDS1555: D101, D108, D204
 D103, D109, D206
 D104, D10, D209
 D106, D203
 1S 34 IN60: D102, D107, D105, D302
 1A/100V, D207, D301



⊥ CHASSIS GND. ⚡ BATTERY NEGATIVE
 * VARIABLE ** CONTROL NOT ACCESSIBLE FROM SIDE

- C347 - C348
 C340 - C344
 C349
 0.01 X 7
 C358
 C359
 C347 - C343
 C367 - C361
 0.047 X 4
 C333
 C344 - 18 P
 C346 - 5 P